



Thunder Mountain Wind & Fire MC, Chapter 81

P.O. Box 802

Loveland, Colorado 80539

April 24, 2016

Cozumel Fire Engine Donation Project:

1985 Ford/Pierce TeleSquirt Fire Engine – Title
Number 12M784934

VIN: 1FDYD80U0FVA07286

Contents:

(34) - 2.5" x 50' Hose - rear cab seats area

Drivers Side:

First Cabinet

- (1) Gated Wye
- (1) LDH Reducer
- (1) LDH Coupler
- (1) LDH Collar
- (1) 2.5" Double Male
- (1) 2.5' Double Female
- (1) 4" x 2.5" reducer
- (1) Female to Male 4"
- (1) Storz to threaded Adaptor
- (1) Rescue Shears
- (1) Rescue Spreader
- (1) Rescue Manifold
- (1) Rescue Manifold
- (1) Rescue Power Unit

Second Cabinet

- (2) 1.75" hose
- (10) Turnout Coats

Third Cabinet

- (16) Turnout Pants
- (2) Turnout Coats

Forth Cabinet

- (9) Turnout Coats
- (1) Spare Gasoline Can

Other Driver's Side

- (2) hose rollers
- (1) 2.5" female to male adaptor
- (6) Leather Hose Jackets
- (2) Reducers
- (1) 5" LDH Cap
- (1) 5" to 4" reducer

Officer's Side:

- (18) 1.75" hose
- (18) Turnout Pants

Front Officer's Seat

- Box #22
 - (2) Pants
 - (22) Shirts
- Box #25
 - (32) Pants
 - (16) Shirts
- (1) Parts Bonly Air Pack
- (2) Boxes of Air Cylinder Valves for new Cylinders

Behind Cab Seats



Thunder Mountain Wind & Fire MC, Chapter 81

P.O. Box 802

Loveland, Colorado 80539

- (12) Turnout Coats
- (3) Pair Boots
- (1) Turnout Liner

Behind Cab Seats (Continued)

- (1) Turnout Pants
- (1) Mesh Rack
- (1) Black Hose Cover Tarp

Top of Water Tank

- Box #8
 - (14) Turnout Coats
- Box #11
 - (16) Turnout Coats
 - (1) Wildland Firefighting Shirt
 - (4) Pairs of Boots
- Box #14
 - (14) Turnout Coats
- (1) Stokes Rack
- (3) 1.5" hose
- (2) 10' Hard Suction Hose